

# Parish Lengthsman Report

## June 2025

Date	<i>Works Complete</i>	Hours
	Preparing monthly report	1
3 <sup>rd</sup>	Carried out a visual check of the underpass and cleared leaves, stones and debris from underpass and all paths leading in to the underpass. Carried out a litter pick of the underpass	½
	Check carried out of the path behind Quantock Brewery plus litter pick	¼
	Check carried out of the woodland walk next to underpass plus litter pick	¼
4 <sup>th</sup>	Mow, strim and tidy areas – All Junctions of Grendon House Road on to A358 All Junctions of Minehead Road on to A358 All of the main roundabout and around the safety fencing Grass around the bus stop by main roundabout	1 ¾ 2 ¼
5 <sup>th</sup>	Mow, strim and tidy areas – All Junctions of Taunton Road on to A358 Area around the Cotford roundabout and visibility on to Dene Road Junction of Wick Lane on to A358 Around the bridge at Wick lane Station green Crossroad of Cushuish Lane and Fennington Lane Around the post and rail fencing outside Middle Brook Farm	¾ ¾ ¼ ¼ ½ ¼ ¼
	Cut vegetation from around the post box on the A358	¼
	Check of signs and vegetation growth around the village	1
	Cleared leaves and debris from the paths both sides of the stream	½
	Cleared leaves and debris off the pavement along Hither Mead	¼
	Cut back vegetation around signs at Stairfoot	¼
10 <sup>th</sup>	Carried out a visual check of the underpass and cleared leaves, stones and debris from underpass and all paths leading in to the underpass. Carried out a litter pick of the underpass	½
	Moved the SID	2
	Removal and cutting of tree from the roof at Millers Way	1
	Preparing (speaking to the doctors surgery and checking access) for and starting to remove vegetation off the toilet roof	1
11 <sup>th</sup>	Mow, strim and tidy areas – Outside public toilets Lydeard Mead bank Grass verge along Taunton Road leading in to Webbers and Mill Lane Mowing strip on the right as you turn down Hither Mead from Taunton Road	¼ 1 ½ ½

	<p>Grass on the left as you turn down Hither Mead from Taunton Road</p> <p>Area at the bottom of Millers Way</p> <p>Footpath between Hamber Lea and Quantock View</p> <p>Footpath at the bottom of Grendon House onto A358</p> <p>Check carried out of the woodland walk next to underpass plus litter pick and cut back overhanging vegetation</p> <p>Removal of tree limb fallen into the road in the village</p> <p>Removal of vegetation off the toilet roof</p>	<p>¼</p> <p>¼</p> <p>¼</p> <p>1 ¼</p> <p>1 ¼</p> <p>½</p> <p>9 ½</p>
17 <sup>th</sup>	<p>Tidy shrubs and clear up - outside the toilets</p> <p>At Darby way</p>	<p>2</p> <p>1 ½</p>
19 <sup>th</sup>	<p>Mow/strim visibility areas –</p> <p>Small car park at Greenway Road near Ash Priors</p> <p>Entrance to the Main car park on Greenway Road near Ash Priors and the Junction on Greenway Road leading to Ash Priors</p> <p>Station green</p> <p>Station road</p> <p>Around the Broadgauge business park sign</p> <p>Junction of West Street on to A358 and Junction of West Street on to Watts Lane</p> <p>Mowing strip on the right as you turn down Hither Mead from Taunton Road</p> <p>Carried out a visual check of the underpass and cleared leaves, stones and debris from underpass and all paths leading in to the underpass.</p> <p>Carried out a litter pick of the underpass</p> <p>Blow and clear debris from top paths way at Hither Mead</p>	<p>¼</p> <p>¾</p> <p>½</p> <p>2</p> <p>¼</p> <p>½</p> <p>2</p> <p>½</p> <p>¼</p>
26 <sup>th</sup>	<p>Cut hedges and tidy –</p> <p>Station green</p> <p>Webbers</p> <p>Carried out a visual check of the underpass and cleared leaves, stones and debris from underpass and all paths leading in to the underpass.</p> <p>Carried out a litter pick of the underpass</p> <p>Cut vegetation around the Bishops Lydeard village sign opposite the football ground</p> <p>Litter pick in lane by entrance of village by the football ground</p>	<p>3</p> <p>1</p> <p>½</p> <p>¼</p> <p>½</p>

## Some work missed from the May report

9<sup>th</sup> – 1 hour

Fitted toilet roll holders

13<sup>th</sup> – 4 hours

Clearing weeds from gravel and borders in the war memorial

20<sup>th</sup> –

Moved SID

Removal of tree branch over hanging road

Cut back vegetation from signs around the village

Drive around village and check for issues

29<sup>th</sup> - ½ hour

Carried out a visual check of the underpass and cleared leaves, stones and debris from underpass and all paths leading in to the underpass.

Carried out a litter pick of the underpass

## Photos of the works completed on toilet roof

